1426-1446 East Baltimore Street (Commercial Buildings)
1434 East Baltimore Street
Baltimore (Independent City)
Maryland

HABS No. MD-904-D

HABS MD, 4- BALT, 153D-

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC REGION, NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PENNSYLVANIA 19106

Form 10-920 (June 1983)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

MD. 4-BALT, 153 D-

ARCHITECTURAL DATA FORM

	ARCHITECT	JRAL DATA FURM		153 D-
STATE	COUNTY		TOWN OR VICINI	
Ma ry land			Baltimo	are
HISTORIC NAME OF STRUCTURE (INCLUOE SOURCE FOR NAME)			<u> </u>	HABS NO.
1426-46 East Baltimore Stree		*1.1•		 MD-904-D
SECONDARY OR COMMON NAMES OF	F STRUCTURE	wiaings)		1 110-304-0
1434 East Baltimore	Street			
COMPLETE ADDRESS (OESCRIBE LO	CATION FOR RURAL	SITESI		
		J		
1434 East Baltimore Stree				
DATE OF CONSTRUCTION (INCLUOE	SOURCE)	AR CHITECT(S) (INC.	LUOE SOURCE)	
C. 1905 (1911 Sanborn mag		Unknown		
SIGNIFICANCE (ARCHITECTURAL AI				
Original use presumed to	be shop with res	sidence above.	Interestingly	1434 is paired with
1436. The stair in 1434 This is thought to be ori	dinal late 19	if for the two bu	Jildings which	share a cornice.
or Legizcane.	gillar. Eate 17	ch c. commercial	building wate	n contributes to
STYLE' <i>(IF ÄPPROPRIATE)</i> Italianas	e influence			
MATERIAL OF CONSTRUCTION (INC.		SYSTEMSI		
Brick bearing walls; wood		<u>-</u>	of wood doors	windows and from
SI E AND DIMENSIONS OF STRUCT				
Overall 16' x 50'	Front 16' x 30	Rear	x 20' (see si	ketch plan)
EXTERIOR FEATURES OF NOTE				
Wood cornice; wood cornic		ont. Red brick,	common bond.	
Segmental-arched window o	penings			
INTERIOR FEATURES OF NOTE (OES	CRIBE FLOOR PLANS	S, IF NOT SKETCHEO)		<u> </u>
Undeterminable			- 	
MAJOR ALTERATIONS AND ADDITIO	NS WITH DATES			•
Rear shed addition circa	1920 (now demo1	ished).		
Storefront alterations				
PRESENT CONDITION AND USE			-	
Currently vacant, this bu	ilding is suffe	ring from extens:	ve water damad	ge. It is unsafe
to enter and inspect. Bu	ilding front app	pears stable	<u> </u>	30
OTHER INFORMATION AS APPROPRI				•
Building is to be demolis		front room and re	built to a new	w design for
cooperative apartments fo	ı driisis.			
SOURCES OF INFORMATION (INCLU	DING LISTING ON MA	TIONAL REGISTER S	TATE REGISTERS	ETC I
THE CHIEF THE PROPERTY OF THE				

COMPILER, AFFILIATION

DATE

Peter C. Doo AlA Walter Schamu & Associates

1869 Sachsey Map, 1887 Bromley Map, Sanborn Maps 1902, 1911, 1927, 1932

23 Sept. 1985

